

Product Safety Recall

Specialized SIRRUS Bikes with Two-Piece Slotted SIRRUS Cranks Model Years 2019-2022



Sold nationally by **Specialized Australia Pty Ltd** via authorised retailers from 1 July 2018 to March 2022

Identifying Features: Affected cranks were sold as original equipment on SIRRUS bikes with Model Years 2019 to 2022. Affected models include:

- MY 2019 - SIRRUS Sport (including EQ and Step-Through versions) and SIRRUS X Comp Carbon
- MY 2020 - SIRRUS Models 3.0, 4.0, X3.0, X4.0 and X5.0
- MY 2021 – SIRRUS Models X3.0 and X4.0
- MY 2022 – SIRRUS Models X3.0 and X4.0

Defect: The cranks may not have been installed to factory specification and may disengage during riding.

Hazard: If the pedal and crank arm fall off while the bicycle is being ridden, the rider may lose control of the bicycle, increasing the risk of an accident or injury.

What to do: Stop using the affected bikes immediately and return them to your nearest Authorised Specialized Retailer for free inspection and repair. For more information, contact Specialized Rider Care at 1300-499-330 or visit www.specialized.com/au/en/safety-notice

See productsafety.gov.au for
Australian product recall information