

Product Safety Recall

2015 Breezer Downtown Bicycles Models: Downtown 3 and Downtown EX



Defect: The bicycle pedal can separate from the spindle (axle) during use.

Hazard: If the defect occurs, this may cause the rider to lose control, posing a serious fall hazard.

What should consumers do?

Consumers should immediately stop using the bicycles and replace the pedals. Oceania Bicycles is no longer operational and there is no avenue for remediation for consumers.

See productsafety.gov.au for
Australian product recall information