

Product Safety Recall



Trolley Jack 2000kg
ARMM800

Sold between July 2015 – August 2017

Defect In some circumstances incorrect safety labels have been fitted that do not carry compliant warnings.

Identification Incorrect labels are marked with the part number **ARMM800A**

Hazard User may not use jack correctly or with appropriate vehicle support stands when working under lifted vehicle. This may lead to serious injury or death to user.

What to do Consumers should contact place of purchase or Repelec Aust, a replacement safety label will be sent out for fitting to the jack.

Contact Details You can contact Repelec Aust by phoning 1300 555 586 Mon-Fri 9.00am to 5.00pm, via email at sales@rushmore.com.au or go to www.armstrongonline.com.au

**See productsafety.gov.au for
Australian product recall information**