

Product Safety Recall

DOMETIC RC1180 3-WAY ABSORPTION FRIDGE/FREEZER

Model affected: RC1180

Quantity affected: 4

When sold: Between 4 Jul 2017 & 28 Feb 2018

Affected serial number ranges:

71206287 to 71206350

71306248 to 71306311

73705021 to 73705088

73904743 to 73904802



Defect:

An internal heat deflector component may be missing.

Hazard:

If the heat deflector component is not fitted, overheating may occur, which could lead to a fire.

What to do:

If you own one of these fridge/freezers, check the serial number on the rating plate located on the rear panel. If your product falls within one of the 'affected serial number ranges' and 'when sold' details above, **discontinue using the product immediately**, and take it to your nearest Dometic service agent for inspection free of charge.

Contact details:

You can find your nearest Dometic service agent by calling **1800 21 21 21** Mon-Fri 8:00am - 5:00pm EST, or via email at gldservice@dometic.com.au

**See productsafety.gov.au for
Australian product recall information**