



PRODUCT SAFETY RECALL

LG Electronics Australia Pty Ltd takes product safety very seriously and wishes to advise customers that it has voluntarily decided to recall the LG side by side refrigerator models listed below.

Defect/Hazard: The micro-switch in the ice maker of identified models could deteriorate causing the ice maker to malfunction and in certain circumstances may result in a fire hazard.

Affected Models:

GR-D267DTU	GR-L207EQ	GR-L247ER	GR-L247TSS	GR-L267NI
GR-G267TV	GR-L207NI	GR-L247NI	GR-L247WH	GR-L267NIS
GR-L197NIS	GR-L207NIS	GR-L247NIS	GR-L247WV	GR-P197WVS
GR-L197VS	GR-L207WV	GR-L247NSS	GR-L247WVS	GR-P277NI
GR-L197WVS	GR-L207WVS	GR-L247TS	GR-L257NI	

Serial Number Range: Please visit www.lg.com.au/fridgerecall for details of affected serial numbers.

Available for Sale: The products were available for sale nationally between **January 2002 until February 2006.**

WHAT TO DO

Customers with affected models are requested to contact the LG Customer Information Line on 1800 506 154, 9am to 5pm (AEST) to arrange for a service technician to replace the micro switch.

Prior to calling, customers are asked to record their model and serial number to provide to LG's Customer Information line. Customers can locate model & serial number on the left hand wall inside the fridge door.

LG Electronics apologises for any inconvenience caused to customers.

See www.recalls.gov.au for
Australian Product Recall Information.