

Product Safety Recall

SP SURE POWER



Battery Separators:

Model 1314 (S/N 09004545—10008041)

Model 1315 (S/N 09002323—10003168)

Sold throughout Australia from August 2009 to June 2011 through ARB Corporation Ltd. including as part of some ARB Dual Battery Tray Kits. Also re-sold (during the same period) by other retailers who are ARB customers.

Defect Some units may have internal circuit board capacitor failure which may lead to overheating, smoke and/or fire during or following use.

Hazard If capacitor failure and overheating, smoke and/or fire occurs, it may result in property damage and/or injury.

What to do Consumers should immediately stop using and/or disconnect the product and contact Sure Power, Inc. to exchange the recalled unit for an equivalent replacement product or full refund.

Contact Details Call Sure Power, Inc. at 1-800-649-913 or e-mail recall@surepower.com or return recalled product to Reply Paid 2577, Sure Power, PO Box 2577, Smithfield NSW 2164 with your name, address and telephone number, specifying preference for replacement or refund.

**See www.recalls.gov.au for
Australian Product Recall Information**