

Product Safety Recall



PRODUCT: MVP Prolift Mechanical Speedy-Lift Trolley Jack – 1800kg

MODEL: F34805M

BATCH NUMBER: 10109

DEFECT: The trolley jacks did not have the full warning and operating instructions included on the jacks as specified in the Australian/New Zealand Standard AS/NZS 2615:2004.

HAZARD: Due to incorrect labelling consumers could misuse product

DATES SUPPLIED: March 2010 – May 2011 in automotive retail and tool outlets nationally

WHAT TO DO: Consumers should cease using this trolley jack immediately and return to the place of purchase for exchange or full refund.

SUPPLIER INFORMATION

Shinn Fu Australia Pty Ltd
15 View Tech Place
ROWVILLE VIC 3178

Telephone: (03) 9755 8277

Contact: David Sleeth

**See www.recalls.gov.au for
Australian Product Recall Information**