

# Product Safety Recall



GA number  
QA000011 – QA007313



Optimus Pump for Nova & Nova+  
(Art. Nr. 8017904)



Optimus Nova  
(Art. Nr. 8016276)



Optimus Nova+  
(Art. Nr. 8016277)



Optimus Repair Kit Nova &  
Nova+  
(Art. No. 8017632 + 8511)



Optimus Nova&Nova+  
Spare Parts Set Light  
(Art. No. 8016305 + 8520)

- **Optimus Nova Stove**
- **Optimus Nova+ Stove**
- **Optimus Pump for Nova and Nova+**
- **Optimus Nova and Nova+ Spare Parts Set Light**
- **Optimus Repair Kit Nova and Nova+**

**Defect:** A sharp edge left over from tooling for the quick-action coupling and the ON/OFF fuel supply valve of the pump may cause the O-rings to tear. Also, the O-rings used in the fuel hose and in the ON/OFF valve on some stoves can expand with the use of certain kinds of fuel. Additionally, some Nova stoves of the latest production lots may have fuel hoses which are not completely crimped and could detach.

**Hazard:** One or more of the defects described above, which result in torn or expanded O-rings, can cause fuel leakage and create a fire hazard to consumers.

**What to do:** Consumers should immediately stop using the affected products and contact Katadyn Products Inc. or Outdoor Agencies Pty Ltd to arrange for replacement parts to be provided.

**Contact Details:** Visit [www.outdooragencies.com.au](http://www.outdooragencies.com.au) and click the Optimus Nova Recall button on the homepage to be redirected to Katadyn Products Inc, or phone Outdoor Agencies on 02 8717 7309 or email at [novarecall@outdooragencies.com.au](mailto:novarecall@outdooragencies.com.au)

**See [www.recalls.gov.au](http://www.recalls.gov.au) for  
Australian Product Recall Information**