

ELECTRICAL SAFETY RECALL



Ariston and Indesit Domestic Tumble Dryers sold in Australia from April 2004

MODELS: ASL70CX(AUS), ASL700CX(AUS), AQCF851BU(AUS), TCF87B6H1(AUS), AQC8BF7T1(AUS), AS60VX(AUS), IS60V(AUSA), AS600VX(AUS), IDV65(AUS), TVF75C6H1(AUS), IDVA735X(AUS)

DEFECT: There is potential for lint/fluff to dislodge from the rear drum seal, fall near the dryer heater and become ignited.

HAZARD: If the lint/fluff is ignited this poses a potential fire hazard.

WHAT TO DO: If you have an affected product, you should unplug and cease using the tumble dryer until a modification has taken place. Arisit will arrange a visit from an engineer, free of charge, to modify your appliance. The service call will take approximately an hour.

If your tumble dryer has already been modified (your dryer will have a green dot sticker on the back or inside of the door of the drum) or you have purchased a replacement machine then no further action is required.

Contact Arisit to arrange a service call.

CONTACT DETAILS: For more information about the recall, consumers should contact Arisit on 1300 762 219 or email ariston.dryer@arisit.com between the hours of operation: Monday-Friday 8:30am to 5pm.

**See www.productsafety.gov.au
for Australian product recall information.**