

Product Safety Recall



Production Date
July 2014



Production Date
August 2014



Pro Quip Standard Plastic Fuel Can Range

Part Numbers: 0950, 1008, 0957, 0951, 1009, 0958, 0805, 0804, 0902, 0903
with a Production Date of July or August 2014 (refer to images above left)

Sold through Automotive Hardware and Specialty Stores
from July 2014 to May 2015

DEFECT: In some circumstances, the Screw Cap (refer to image above left) may split when tightened or sealed

HAZARD: If the defect occurs, the contents may leak or spill, exposing consumers to hazardous fumes and posing a potential fire hazard.

WHAT TO DO: Consumers should check the Production Date on the bottom or underside of the Can, and immediately contact Pro Quip to arrange a replacement Cap if their Can is affected by this notice.

CONTACT DETAILS: You can contact Pro Quip by phoning (03) 9761 1110 (Mon-Fri 9am – 5pm), by email at recall@proquip.com.au, or go to www.proquip.com.au

See www.recalls.gov.au for
Australian Product Recall Information