


Electrical Safety Recall

Sunbeam Café Espresso II coffee machine model EM3820

Sold between February 2013 and March 2014. These machines can be identified by the name 'Café Espresso II' or by the model number 'EM3820' and the 3-digit production code (**XXX**) which appears on the label. Only production codes **033**, **103**, **113**, **153**, **293** and **323** are being recalled.



Defect: Movement of the milk-frothing wand may cause abrasion of wiring inside the machine, resulting in failure of insulation.

Hazard: Risk of electric shock.

What to do: Stop using the machine, unplug it from the wall and contact Sunbeam- refer contact details below.

Contact details: Customers can call 1300 882 570 (8:30am to 5:00pm AEST Monday to Friday) or visit www.sunbeam.com.au/recall for further information and assistance. A replacement machine of similar value will be provided free of charge.

See www.recalls.gov.au for Australian product recall information.

Sunbeam Corporation sets itself exceptionally high standards in terms of quality and safety and sincerely apologises for the inconvenience this recall may cause.