

Electrical Safety Recall

B-Well Steam Steriliser



Medela AG is issuing a recall on B-Well Steam Sterilisers sold between May 2012 and December 2013 in Australia through various retailers.

The affected products can be identified by either the model number or the article number.

Models affected: 200.3377 or 200.3378

Article numbers affected: 008.0100, 008.0101, 008.0102, 008.0103, 008.104, 008.0121 and 008.0287

Product issue: Moisture may enter electronics or power cable and may cause a short circuit or a high leakage current.

Hazard: Potential risk of burn, fire or electric shock.

What should I do? Stop using the B-Well Steam Steriliser immediately and unplug it from the socket outlet.

Customers should return the B-Well Steriliser to the point of purchase, or contact Medela Australia (details below) for a full repayment of the purchase price. For further information or queries concerning this notice, please contact Medela Australia on 1800 787 345 between 9 am and 5 pm EST Monday to Friday, fax 03 9552 8699 or email to contact@medela.com.au or bwell@medela.ch.

See www.recalls.gov.au for
Australian Product Recall Information