

Product Safety Recall

le cornuTM
since 1854



Nexus Bunk Bed

Sold 1st June 2012
to 15 April 2013

Defect: The Australian Standard for bunk beds requires that:

- protrusions not exceed 8mm;
- the vertical distance between the guard rail and label indicating the maximum height of the mattress must be at least 160mm; and
- the country of origin and the Australian distributor's name and address be permanently and indelibly marked.

In a batch of the "Nexus" bunk beds sold between the dates mentioned above, the protector cap fitted to the upright corner post causes the post to protrude above the rail of the top bunk by 8.9mm, in some instances the location of the mattress label was found to be less than the minimum required distance and the distributor's name and address and country of origin labels did not comply or may not have been supplied.

Hazard: The protrusion may snag clothing of the occupant of the top bunk which may cause personal injury and the inaccurate label positioning may lead to an incorrect size mattress being used on the top bunk which could lead to a falling hazard.

Action: Le Cornu Furniture will supply replacement protector caps that reduce the height of the protrusion to less than 8.0mm, labels that indicates the correct vertical distance between the guard rail and the maximum height of the mattress will be supplied, together with country of origin and Australian distributor's name and address label.

The top bunk should not be used without adult supervision until the replacement cap and mattress height label is affixed.

Contact details: For more information please contact Le Cornu by:

- Email: customerservice@lecornu.com.au
- Telephone: 08 8292 3300
- In writing to: Le Cornu Furniture and Carpet Centre PO Box 296, Keswick SA 5035.

**See www.recalls.gov.au for
Australian Product Recall information**