

Product Safety Recall



Chicco KeyFit Plus Infant Car Seat – Tether Anchor Bracket

Sold nationally through independent nursery hardware retailers between
1st September 2012 – 14th November 2012

Product information:

The single style manufactured after XX June 2012. There is a date of manufacture label on the underside of the car seat. Model number: 379046.46.42 in Graphica colour only.

What are the defects?

Batch 22 of the tether anchor bracket is faulty. The tether anchor bracket connects the car seat tether strap to the car anchorage bolt.

What are the hazards?

If the tether anchor bracket fails in the event of a collision, the performance of the car restraint may be impacted increasing the risk of injury to the child.

What should consumers do?

If you are using the tether anchor bracket supplied with the booster seat you should check the batch number stamped on it. If the batch number is "22", cease using the booster seat immediately.

Contact Chicco by phone on 02 8543 5570 or email info@chicco.com.au to arrange for a replacement tether anchor bracket to be sent to you.

See www.recalls.gov.au for
Australian Product Recall Information