

## Product Safety Recall



**Polaris Youth All-Terrain Vehicles (ATVs) MY2001 – 2017:  
Outlaw 50, Outlaw 90, Outlaw 110, Sportsman 90,  
Sportsman 110, Phoenix 200, Sawtooth 200, Predator 50,  
Predator 90, Scrambler 50, Scrambler 90.**

Sold at authorised Polaris Dealers since 2000.

**Defect:** Parts used in vehicles may contain asbestos (front brake shoe/pad, rear brake shoe/pad, heat shield washer, arrestor gasket).

**Hazard:** Currently available information indicates that the products pose no measurable asbestos-related health risk during use of the vehicles. Caution must be taken if carrying out repairs/maintenance.

**What to do:** Any work involving these vehicles should be carried out by an authorised Polaris dealer. Procedures will be implemented to ensure that the vehicles are handled correctly by Polaris dealers. Affected consumers should contact their local Polaris dealer for an appointment to have the affected parts replaced at no charge.

**Contact details:** For further information consumers can call the Customer Service Department on 1800 982 593 or go to [www.polarisindustries.com.au](http://www.polarisindustries.com.au).

**See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information**