



Product Safety Recall



Do you own this product?

SME Mowers – Bobcat lawn mowers

Kawasaki general engines with voltage regulator (part no. 21066-0785) installed in ZT6000 and ZT7000 Bobcat lawn mowers.

Affected Bobcat lawn mower models:

- 9996010 – ZT6000
- 9996012 – ZT6100
- 9997010 – ZT7000
- 9997011 – ZT7000

Dates sold: 1 November 2021 – 11 January 2024



Why the product is recalled: The voltage regulator in affected Kawasaki general purpose engines, installed in select Bobcat lawn mowers, can malfunction. The affected mowers can catch fire at any time, even if the engine is off or not in use.

Hazard: There is risk of serious injury, death and/or damage to property if the voltage regulator catches fire.

Action required:

1. Stop using the affected mower until it has been repaired.
2. Disconnect the negative battery cable and secure it away from the negative battery post. If you are unsure on how to disconnect the battery, see the [battery disconnection instructions](#) or contact your local Bobcat lawn mower dealer.
3. Contact your local Bobcat lawn mower dealer to arrange repair.

Repairs are expected to commence from mid-April 2024 when replacement voltage regulators become available.



For more information contact SME Mowers via email sales@smemowers.com.au or phone 1800 088 567 (8:00am to 4:30pm, Monday to Friday).



Purchased from: Bobcat lawn mower dealers

PRA 2024/20153

See productsafety.gov.au for
Australian product recall information