



Product safety recall

Certain P&A Kits for Profile Low Rear Suspension (P/N 54000134) or P&A Tall Rear Shock (P/N 54000294) intended for installation on certain Softail motorcycles.

Harley-Davidson Australia Pty Ltd

Certain parts and accessory kits (P&A Kits) for Profile Low Rear Suspension (P/N 54000134) or P&A Tall Rear Shock (P/N 54000294) intended for installation on certain Softail motorcycles (see below):

- P/N 54000134 - Fits 2018-later FLHC, FLHCS, FLHCS ANV and 2024 FLI models
- P/N 54000294 - Fits 2018-later Softail® models (except FXFB, FXFBS, FLFB and FLFBS)



Reason the product is recalled

The rear shock pre-load adjuster mounting bracket may fracture and allow the rear shock adjuster to contact the rear tire.

The hazards to consumers

Risk of serious injury or death from a crash if contact between the rear shock adjuster and tire occurs.

What consumers should do

1. Stop using motorcycles fitted with these parts immediately.
2. Contact your nearest Harley-Davidson dealer to schedule a free repair.
3. To find a local dealership, visit <https://www.harley-davidson.com/au/en/tools/find-a-dealer.html>

Contact

Harley-Davidson Australia Pty Ltd

Call 02 9886 0600 between 8 am and 5 pm

Email reception.sydney@harley-davidson.com

Visit <https://www.harley-davidson.com/au/en/tools/find-a-dealer.html>

Who sold the product: Harley-Davidson Australia Pty Ltd

Dates available for sale: 24 January 2017 to 13 December 2024

PRA2025/20559

See productsafety.gov.au for Australian product recall information