



# Product Safety Recall



## Do you own this product?

**MY2022 and 2023 Can-Am Commander series, Defender series, Maverick Trail series Side-by-Side vehicles**

MY2022 and 2023 Can-Am Side-by-Side vehicles:

Commander series

Defender series

Maverick Trail series

Dates sold: 3 May 2022 to 13 October 2023



**Why the product is recalled:** The operator's guide maintenance schedule section contains incorrect information about driven clutch pulley maintenance intervals.

**Hazard:** There is a risk of serious injury if the clutch fails due to delayed maintenance and fragments being ejected from the vehicle.



BRP will send registered vehicle owners a notice by mail with a revised maintenance information booklet.

Consumers should ensure that that BRP has their current contact details.



For further information or to receive the revised maintenance information booklet, please contact BRP on [infobrpaustralia@brp.com](mailto:infobrpaustralia@brp.com) or by phone on 1800 531 996.



Purchased from: Authorized BRP Can-Am dealers

PRA2023/19967

See [productsafety.gov.au](https://productsafety.gov.au) for  
Australian product recall information