



Product Safety Recall

Do you own this product?



Brompton T Line bike

Brompton T line folding bike with titanium frame and carbon fibre components.

Affected bikes were manufactured before 21 June 2024 and have a serial number ranging from 2104190001 to 2406070001. The 'T' logo for T line bikes and the serial number can be found on the label on the back of the vertical seat tube.

Dates sold: 1 February 2022 – 24 July 2024



Why the product is recalled: The affected bikes steerer clamp can become loose, causing the handlebar support and fork to become misaligned which can lead to a loss of steering control.

Hazard: There is a risk of accident and serious injury if the rider loses steering control while the bike is in use.



1. Consumers should stop using the bikes immediately and visit <https://global.brompton.com/legal/t-line-recall> to identify whether their bike is affected.
2. Affected consumers can have the repair carried out free of charge at a Brompton dealer.
3. Consumers who have a bicycle torque wrench and are comfortable completing the repair themselves should follow the instructions on the recall website to tighten their steerer clamp hinge bolts.
4. Consumers who are not comfortable completing the repair themselves or who may not be able to visit a Brompton dealer can contact Brompton for assistance in arranging a repair. Contact details can be found here: <https://global.brompton.com/support/contact-us/email>
5. Consumers should verify if their bike has been repaired by searching the Serial Number Tracker, or register if the bike repair has been completed at <https://global.brompton.com/legal/t-line-recall>



For more information contact Brompton:
<https://global.brompton.com/support/contact-us/email>



Purchased from: Brompton Junction Melbourne and Omafietts.

PRA2024/20259

See productsafety.gov.au for
Australian product recall information