

Product Safety Recall

GASGAS MC125 Motorcycles MY2022



Sold by authorised GASGAS dealers
between 19 May 2021 and 11 March 2022

This recall was extended on 27 September 2022 to include additional vehicles.

Defect

Due to the rev limiter setting, the engine's connecting rod (conrod) may break or fracture.

Hazard

A broken connecting rod may cause the engine to suddenly fail, increasing the risk of an accident resulting in injury or death to the rider or others.

What to do

Consumers will be contacted by GASGAS (KTM Australia) or an authorised dealer to arrange an appointment for repair, free of charge. Consumers that have an affected vehicle can also contact an authorised dealer to make an appointment to have it repaired, free of charge.

Contact details

For more information, contact KTM Australia on 1800 644 771 or find the nearest authorised dealer using the dealer search option at <https://www.gasgas.com/en-au/dealer-search.html>

See productsafety.gov.au for
Australian product recall information