



Product Safety Recall

Do you own this product?



Side by side utility vehicles

2024 models:

- Ranger 1000
- Ranger XP 1000
- Ranger XP Kinetic
- Crew 1000
- Crew XP 1000

Dates sold: 14 May 2024 – 28 June 2024



Why the product is recalled: The seat belt buckle bracket on affected vehicles may have a faulty weld.

Hazard: There is a risk of serious injury if the seat belt buckle anchor point separates from the vehicle frame.



1. Consumers should stop using the vehicle immediately.
2. Contact your [authorised Polaris dealer](#) to schedule an inspection. If the seat belt bracket fails the inspection, the Polaris dealer will replace the bracket.
3. Consumers should not attempt repairs themselves. Repairs must be done only by an authorised Polaris dealer.



Ask our staff to find out more about the recall.

<https://www.polarisaustralia.com/find-a-dealer/map-view>



Purchased from: Authorised Polaris Dealers

PRA2024/20286

See productsafety.gov.au for
Australian product recall information