



Product Safety Recall

Do you own this product?

Avanti & Malvern Star MY 2021-24 & Scott MY 2022-24 bicycles

Dates sold: 1 Jul 2020 – 1 Aug 2024



Avanti Black Thunder LE



Avanti Black Thunder LE



Avanti Montari Jr



Avanti Montari Jr



Malvern Star Axis 2



Malvern Star Axis 2 MS



Malvern Star Freedom W2



Malvern Star Freedom M2



Scott Roxter 26



Scott Contessa 26



Why the product is recalled: Over time air may enter the brake hydraulic system or fluid may leak from the brake lever or calliper which can cause a loss in braking power.

Hazard: Risk of accident and serious injury if the brakes do not work as expected.



1. Consumers should stop riding the bicycle immediately.
2. Contact Sheppard Cycles Australia to arrange for replacement brakes to be fitted.



Ask our staff to find out more about the recall.

rework@sheppardcycles.com

1300 883 305 9 am to 5 pm Monday to Friday



Purchased from: Authorised Avanti, Malvern Star & Scott dealers



Set yourself a reminder to check at home

- Take a photo of this notice
- Set a reminder on your phone

PRA 2024/20266

See [productsafety.gov.au](https://www.productsafety.gov.au) for
Australian product recall information