



Product Safety Recall

Do you own this product?



Kaymar rear wheel carrier for 4WD vehicles

Dates sold: 1/5/2022 – 30/11/2022

Affected carriers include those suited to

- Landcruiser 60, 75, 76, 78, 80 and 100 series
- Toyota Hilux 2015 onwards
- Toyota Prado 150
- Ford PX Ranger

See [productsafety.gov.au](https://www.productsafety.gov.au) for a list of affected part numbers.



Why the product is recalled: Welds in the product may fail or break causing the arm of the bracket and wheel to bend away from the vehicle or detach from the vehicle completely.

Hazard: Risk of serious injury to road users or bystanders if the wheel carrier bends or detaches while driving the vehicle. There is an increased risk of an incident if the vehicle is being used in off-road activities due to repeated severe, sudden and jerking movements.



1. Consumers should stop using the product to carry a wheel.
2. Consumers should contact Kaymar 4WD Accessories to arrange an inspection and replacement.
3. Consumers can contact Kaymar 4WD Accessories by phone on 1300 583 973 or email recall@kaymar.com.au



Purchased from: various automotive and 4WD parts and accessory dealers.

See [productsafety.gov.au](https://www.productsafety.gov.au) for a list of traders that sold this product.



Set yourself a reminder to check at home

- Take a photo of this notice
- Set a reminder on your phone

PRA 2023/19819

See [productsafety.gov.au](https://www.productsafety.gov.au) for
Australian product recall information