

Product Safety Recall



Nikon SB-103 Nikonos Speedlight

Sold at Camera House between June 1984 and July 1994

Defect in some extremely rare cases, the front of the flash head may pop out, resulting in a burst incident.

Hazard the batteries may emit hydrogen gas (for example, if NiCd batteries with differing charge levels are used). When this gas mixed with the air inside the SB-103 and the SB-103 was fired, spark generated by the flash head could cause the front of the flash head to pop out, resulting in a burst incident.

What to do Consumers should stop using the product and contact Nikon Australia. Nikon Australia will purchase the product from consumers (incl. freight).

Contact details you can contact Nikon Australia by phoning 1300 401 200 Mon-Fri 9am to 5pm, by emailing Service.Nau@nikon.com or go to www.nikon.com.au.

**See productsafety.gov.au for
Australian product recall information**