



Product Safety Recall

Polaris Spare Parts for Youth All-Terrain Vehicles (ATVs):
Part numbers: 0450422 (front brake shoe), 0450434 and 0452705 (rear brake shoe), 0453861 (heat shield washer), 0454664 (front brake pad).

Sold at authorised Polaris Dealers since 2000.

Defect: Parts may contain asbestos.

Hazard: Currently available information indicates that the products pose no measurable asbestos-related health risk during use of vehicles containing the parts. Caution must be taken if carrying out repairs/maintenance.

What to do: Any work involving these parts should be carried out by an authorised Polaris dealer. Procedures will be implemented to ensure that the parts are handled correctly by Polaris dealers. Affected consumers should contact their local Polaris dealer for an appointment to have the affected parts replaced at no charge.

Contact details: For further information consumers can call the Customer Service Department on 1800 982 593 or go to www.polarisindustries.com.au.

**See productsafety.gov.au for
Australian product recall information**