



Product Safety Recall



Do you own this product?

MAP Automotive remotes and shells

Replacement automotive remotes and shells for various vehicles

45 different remote types are affected. The photo on this notice is of only 1 of the affected models. Check the list below to see if yours is recalled.

Dates sold: 22/06/2022 – 30/04/2023

Models				
KF105	KF200	KF218	KF302	KF365
KF113	KF202	KF219	KF316	KF375
KF114	KF203	KF220	KF318	KF376
KF122	KF204	KF240	KF319	KF378
KF133	KF205	KF241	KF320	KF386
KF134	KF212	KF242	KF325	KF395
KF135	KF213	KF250	KF330	KF910
KF136	KF215	KF268	KF331	KF911
KF150	KF217	KF274	KF361	KF921

Some models listed here are also recalled because they don't meet the mandatory safety standard for products containing button/coin batteries.

Check recall [PRA 2023/19959](#) to see if your product is affected.



Why the product is recalled: The product was sold without the warning information required for products containing button/coin batteries.

Hazard: There is a risk of choking, severe internal burn injuries or death to young children if they gain access to the button batteries and ingest them. Consumers may be unaware that the product contains a button battery.



Consumers should contact Mechatronics Auto Parts on sales@maparts.com.au or by phone on (03) 8792 6999 for a copy of the warning information.



Purchased from: Auto One, Autobarn, Bapcor, GPC Asia Pacific (including Repco), Supercheap Auto, Veale Auto Parts and Wesfil.

PRA2023/19827

See [productsafety.gov.au](https://www.productsafety.gov.au) for Australian product recall information