

Product Safety Recall



Cub Cadet Pro Z 100 Series Commercial Ride On Lawn Mower - extended recall

Sold through Cub Cadet dealerships: October 2016 - December 2018
and March 2022 - July 2022 (Pro Z 154 S only)

Product	Model
Pro Z 148 S	53AWEFJF330
Pro Z 154 S	53AWEFJA330

Defect The lawn mowers were incorrectly supplied with a single direction vented fuel cap. The proper fuel cap should be a dual direction vented fuel cap.

Hazard Pressure may build up inside the fuel tank and fuel might escape if the fuel cap is released too quickly, potentially causing an injury. Fuel leaking from the fuel tank may also pose a fire risk.

What to do Consumers should exercise caution when using their Mower. MTD will send replacement dual direction vented fuel caps, free of charge, via post. If consumers plan on using their Mower in the interim, they should:

- store the Mower in a cool place, preferably indoors, out of direct sunlight.
- not fill the fuel tanks more than half way. Wipe up any fuel spillage and wait at least 5 minutes before starting the Mower.
- maintain a firm grip on the fuel cap and slowly loosen it in order to allow any pressure build up to release.
- if fuel starts to escape, tighten the fuel cap and contact MTD immediately.

Contact details For details of Cub Cadet dealerships, visit www.cubcadet.com.au/dealer-locator. Call MTD Products Australia Pty Ltd on 1300 951 594 Mon-Fri 9am-5pm or email Luke.Turner@sbdinc.com

See productsafety.gov.au for
Australian product recall information