

# Product Safety Recall

Polaris RZR Pro XP 4 MY2021-2022



52 affected vehicles  
Sold between 28 February 2021 and 24 November 2022  
This recall was updated on 24 March 2023 to include extra vehicles and extended dates of sale.

**Defect:**

Fuel may leak from the fuel pump joint.

**Hazard:**

If fuel leaks near an ignition source it may cause a fire or explosion, increasing the risk of serious injury or death to vehicle occupants.

**What to do:**

Consumers should not operate their vehicle. Consumers should contact their preferred Polaris dealer and arrange a time to book their vehicle in for repairs.

**Contact details:**

To find a local dealer, visit [www.polarisaustralia.com/find-a-dealer/list-view/](http://www.polarisaustralia.com/find-a-dealer/list-view/) or call 1300 654 142.

For further information, consumers should contact Polaris Customer Service on 03 9394 5671.

See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information