

# Product Safety Recall

## Honda EU22i Generator

Supplied by Honda Australia Motorcycle and Power Equipment  
Dealers between 2/01/2018 and 27/02/2019



**Defect:** Loose or incorrectly installed screws may result in fuel leaking from the Fuel Cock during operation, storage or transportation of the Generator.

**Hazard:** Potential risk of exposure to flammable liquid (Petrol) and fire.

**What to do:** Consumers should contact their nearest Honda Power Equipment Dealer and arrange an appointment to have the Fuel Cock replaced at no charge.

For help finding a Honda Australia MPE Dealer, consumers can go to <https://mpedealers.honda.com.au/>

**Contact Details:** For further information contact Honda Australia MPE at <https://powerequipment.honda.com.au/contact.aspx> or contact Honda directly on 1300 559 846

See [productsafety.gov.au](https://productsafety.gov.au) for  
Australian product recall information