

Product Safety Recall

Mitsubishi Wiring Harness



Installed on Mitsubishi MR and MQ Triton MY2015-2019 vehicles
Sold by Mitsubishi Motors Australia between 3 February 2015 and 2 December 2019

Defect:

Due to incorrect installation, the genuine accessory towbar wiring harness (where fitted) may allow liquids to contact the electrical circuits. This may cause the harness and its surrounds to overheat, burn or catch fire.

Hazard:

If the tow bar wiring harness or its surrounds burn or catch fire, there is a risk of injury to vehicle occupants and other road users.

What to Do:

Mitsubishi Motors Australia will write to affected owners and advise them to present their vehicle to their preferred dealer to have the wiring harness reinstalled, free of charge.

Contact Details:

For more information, contact your preferred Mitsubishi Motors Australia dealer on 1300 131 211, Option 2, Option 2, or contact Mitsubishi Motors Australia Customer Care on 1800 931 811.

To find a local dealer, visit <https://www.mitsubishi-motors.com.au/customer-assistance/locate-a-service-centre>

**See [productsafety.gov.au](https://www.productsafety.gov.au) for
Australian product recall information**