

Product Safety Recall



**Sea-Doo GTX 230 and 300, RXT 230 and 300, and Wake PRO 230
Watercrafts MY2019**

**Please note that this recall supersedes the previous recall.
All vehicles previously inspected and repaired need to be repaired again.**
Available for sale by BRP between 1 August 2018 and 29 February 2020

DEFECT The intake grate may detach from the vehicle whilst in use.

HAZARD Riding at speeds over 88km/h without an intake grate may cause unpredictable vehicle behaviour. This may lead to occupant ejection, increasing the risk of serious injuries or death.

WHAT TO DO Consumers should avoid operating the vehicle at speeds in excess of 88km/h. All vehicles already inspected or repaired for previous intake grate recall need to be repaired again.

Consumer should contact an authorised Sea-Doo dealership to determine if their vehicle is affected and arrange a time to have their watercraft repaired, once parts are available (from mid April 2020).

Contact details To find a local Sea-Doo dealer, visit <https://au.sea-doo.com/dealer-locator.html>

**See productsafety.gov.au for
Australian product recall information**