


ELECTRICAL SAFETY RECALL

HiKOKI Multi Port Charger

Model UC18YTSL



Double insulation mark

IDENTIFICATION:

Model UC18YTSL marked with **double insulation mark** on the name plate sold nationally through retailers from 12 August 2019 to 2 December 2019. Other batches not affected.

DEFECT:

The battery charger does not comply with the relevant mandatory electrical standard. There is no earth cable inside the power cord and some products may not have been earthed correctly.

HAZARD:

Risk of electric shock which can cause serious injury or death.

ACTION REQUIRED:

Consumers should immediately stop using the charger and check the double insulation mark to identify if charger is a recalled product. Return affected product to place of purchase or your nearest reseller or HiKOKI Power Tools Australia for a refund or replacement cable fitted.

For further information

Please direct all calls and any queries concerning this recall to:
HiKOKI Power Tools Australia Pty Ltd on 1300 444 822 or email
enquiry@hikokipowertools.com.au

See www.productsafety.gov.au for Australian product recall information