

Product Safety Recall

Polaris RZR Multi-Point and Four-Point Harness Kits



Sold by authorised Polaris dealers
between 9 September 2016 and 22 July 2020

Defect The seat belt harness may be missing stitching at attachment points.

Hazard The seat belt harness may not properly restrain an occupant, increasing the risk of serious injury or death in the event of an accident.

What to do Consumers should stop using their vehicle and contact an authorised Polaris dealer to arrange for an inspection and, if necessary, replacement of the seat belt harness.

To find a local dealer,
visit <https://www.polarisaustralia.com/find-a-dealer/list-view/> or phone 1300 654 142.

Contact details Consumers should contact Polaris Customer Service on 03 9394 5671.

See productsafety.gov.au for
Australian product recall information