

# ELECTRICAL SAFETY RECALL

## Solar Power Diverter

SolarImmersion<sup>®</sup> MKIV Power Diverter



### IDENTIFICATION:

Units sold from March 2016 to July 2018

### HAZARD:

If an electrical fault and overheating occur, the plastic cover may catch fire, increasing the risk of injury.

### ACTION REQUIRED:

Stop using your SolarImmersion Power Diverter until the plastic cover has been replaced by a metal cover.

Contact the licensed electrician or solar installer that installed the SolarImmersion unit to organise replacement with a metal cover.

### For further information

Please direct all calls and any queries concerning this recall to  
**Malabou Limited (NZ) via [admin@enhancedenergy.co.nz](mailto:admin@enhancedenergy.co.nz)**

See [www.productsafety.gov.au](http://www.productsafety.gov.au) for Australian product recall information