


ELECTRICAL SAFETY RECALL

FESTOOL Mitre saws, models KS 88 and KS 120



IDENTIFICATION: FESTOOL Mitre saws, models KS 88 and KS 120, manufactured from 2007 to 02/2010 and supplied by Tooltechnic Systems Australia Pty Ltd

DEFECT: Some saws have been manufactured with electrical resistors and varistors that can be damaged by fluctuating voltages while connected to mains electricity. These damaged components can then become hot or start to smoulder if they continue to experience fluctuating voltage. If left connected to the mains for an extended period of time, the saw may overheat and cause a fire.

HAZARD: Injury to the user may occur due to melted or smouldering parts or fire. Property damage could also occur.

ACTION REQUIRED:

1. Stop using the saw and disconnect from the mains.
2. Contact Festool via www.festool.com/retrofit or Tooltechnic on 1300 063 900 to register your details for free modification of the saws to make them safe. Modification works will commence from March 2021.
3. If you no longer have the saw, please contact us immediately and provide the details of the person who has the saw so that we can contact them.

CONTACT:

Festool will be contacting all known owners of affected saws. A repair will be available for affected saws from mid-March 2021. The repair, postage and safety check will be free of charge.

To check if your product is affected please enter the part number (T-No.) and serial number (S-No.) of your Mitre Saw on our website. For further information visit www.festool.com/retrofit and select 'Australia'.

**See www.recalls.gov.au for
Australian Product Recall Information**