

Product Safety Recall

**COOPER –
DISCOVERER
AT3 4S**



**MICKEY
THOMPSON –
DEEGAN 38
ALL- TERRAIN**



Identification: The affected tyres are motor vehicle tyres produced from 1 February 2018 through 1 December 2019.

BRAND	LINE	SIZE	DOT IDENTIFICATION CODE			
COOPER	DISCOVERER AT3 4S	275/55R20	UT	Y1	1M0	0518--1218 1518--1818 2418--3119 3319--3619 4219--4419
MICKEY THOMPSON	DEEGAN 38 ALL-TERRAIN	275/55R20	UT	Y1	MDP	2818--4118 1119--1519 2719--3119 3319--3619 4219--4419
MICKEY THOMPSON	DEEGAN 38 ALL-TERRAIN	275/65R18	UT	YJ	MDN	2218 3618--3718 0219--0419 1019 1919--2019 2719--2819

To determine if your tyre is subject to this recall, please find the tyre's DOT Identification Number which is located on the lower sidewall of the tyre. The affected DOT serial numbers of the affected tyres are detailed in the above table and end with a four digit date code (2-digit week and 2-digit year).

The following example depicts a DOT Identification Number ending with 3718 for illustration purposes only.



Defect: The tyres may develop bulges and separation of the tyre sidewall may occur. This may lead to rapid pressure loss or reduced performance in the tyre.

Hazard: If this occurs, this can result in loss of vehicle control, which may increase the risk of serious injury or death to vehicle occupants and other road users.

What to do: If you believe you have an affected tyre, please immediately contact Exclusive Tyres at 1300 756 884 to arrange for identification and replacement of any affected tyres free of charge.

Contact: For further information, please go to www.coopertires.com.au or www.mickeythompsonstires.com.au or call 1300 756 884.

**See productsafety.gov.au for
Australian product recall information**