

# Product Safety Recall

Continental Sport  
Contact 5 SUV AO



General Grabber AT3



**IDENTIFICATION:** Affected tyres bear the DOT Serial in combination with the Date Code and Mould Number specified below:

Brand	Size and Pattern	DOT Serial	Date Code	Mould Number
Continental	255/45R20 101W Sport Contact 5 SUV AO	A312 BH52	0620	418766
General	LT265/75R16 123/120S Grabber AT3	A3W8 HMRD	1718	415948

The specified Continental tyre was sold between 1 April of 2020 and 16 March 2021 and the specified General tyre was sold between 1 June of 2018 to 16 March 2021.

**DEFECT:** Due to a manufacturing defect, the tire sidewall may break or degrade. This may lead to rapid pressure loss or reduced performance in the tyre.

**HAZARD:** If there is a rapid pressure loss or the tyre degrades this may lead to tyre failure, resulting in loss of vehicle control. This may increase the risk of serious injury or death to vehicle occupants and other road users.

**WHAT TO DO:** If you believe you have an affected tyre, please immediately contact Continental to arrange for identification and replacement of any affected tyres, free of charge.

**CONTACT DETAILS:** For further information, contact Continental by phone, toll free on 1800 316 372.

See [productsafety.gov.au](https://productsafety.gov.au) for  
Australian product recall information