

Product Safety Recall

Öhlins Front Suspension Struts

Part numbers beginning with POS 5N20

Sold as part of suspension kits for installation on
certain Porsche vehicles

(Kit Part No. POZ MN02 and POZ MN05)



Sold by Steve Cramer Products and Sideline Design Ltd
t/as Design 911 and as PPCGB
between 25 February 2015 and 4 February 2020

Defect Due to incompatibility between the front suspension struts and the vehicle top mount, the strut pins may fatigue under maximum steering and break.

Hazard If the pin fails, the strut will separate from the vehicle and front wheel control will be lost, increasing the risk of an accident causing or injury or death to the vehicle occupants and other road users.

What to do Consumers should contact Öhlins to arrange for replacement suspension struts and top mount. Öhlins will cover the cost of installation of the replacement kit.

Contact details For more information, consumers can contact Öhlins on ohlins_asia@driv.com

See productsafety.gov.au for
Australian product recall information