

Product Safety Recall



Husqvarna Model EE-5 Motorcycles MY 2021

To be sold by authorised Husqvarna dealers.

Defect: The battery vent valve may be missing on some motorcycles, allowing water intrusion.

Hazard: If the vent valve is not fitted, water could enter the battery and result in a short circuit, affecting the vehicle operation. A short circuit can increase the risk of an accident, causing injury or death to the rider or others.

What to do: All affected motorcycles that have not been sold will be inspected and repaired (if needed) before sale. If affected, consumers will be contacted by dealerships, advising them of the recall and asking them to contact an authorised Husqvarna dealer to arrange an appointment for inspection of their motorcycle.

Contact details: For further information, consumers can contact Husqvarna Australia on 1800 644 771 or find their nearest authorised dealer using the dealer search option at <https://www.husqvarna-motorcycles.com/au>

**See productsafety.gov.au for
Australian product recall information**