

Product Safety Recall



KTM Model SX-E 5 Motorcycles MY2021

Sold by authorised KTM Australia dealers 1 Nov 2020-24 Dec 2020

Defect: The battery vent valve may be missing on some motorcycles, allowing water intrusion.

Hazard: If the vent valve is not fitted, water could enter the battery and result in a short circuit, affecting the vehicle operation. A short circuit can increase the risk of an accident, causing injury or death to the rider or others.

What to do: Affected consumers have been contacted by dealerships, advising them of the recall and asking them to contact an authorised KTM dealer to arrange an appointment for inspection of their motorcycle. Affected motorcycles that have not been sold will be inspected and repaired (if needed) before sale.

Contact details: For further information, consumers can contact KTM Australia on 1800 644 771 or find their nearest authorised dealer using the dealer search option at <https://www.ktm.com/au>

**See productsafety.gov.au for
Australian product recall information**