

# Product Safety Recall

## Mercury Outboard FourStroke 75, 90, 100, 115, 135 and 150hp Engines MY2021

Models Covered	Serial Number Range
75 - 115hp	3B034165 to 3B084339
135 - 150hp	3B021624 to 3B067243

75hp - 115hp	115hp ProXS	75hp-115hp SeaPro
		
135hp - 150hp	150hp ProXS	150hp SeaPro
		

**Defect** The engines may have been fitted with an Idle Air Control Valve (IAC) that is out of specification. An out of specification IAC may prevent the engine from returning to a slow idle speed after the engine has been run at a higher speed, meaning the engine speed may remain much higher than normal.

**Hazard** If the engine speed remains higher than normal, it may be difficult to shift out of gear and into neutral. This could lead to loss of control of the boat, increasing the risk of an accident and injury

**What to do** Consumers with affected engines requiring repair should stop using their boat. Owners of affected engines have been contacted in writing by Marine Power International to request that they contact an authorised Mercury Marine dealer to schedule a service appointment. Please mention Mercury Service Outboard Bulletin 2021-04R1.

**Contact details** Contact Mercury Marine Customer Service on 03 9791 5822 (Monday to Friday, 8:30am - 4:30pm AEST) or by email at [merc.info@mercmarine.com](mailto:merc.info@mercmarine.com)  
To locate a Mercury Marine dealer, visit <https://www.mercurymarine.com/en/au/find-a-dealer>

**See [productsafety.gov.au](https://productsafety.gov.au) for  
Australian product recall information**