

# Product Safety Recall

**Aeroad CF SLX R081  
(Cockpit CP0018) and Aeroad CFR  
R065 (Cockpit CP0018) Road Bikes**



**Sold by Canyon Bicycles  
between 1 October 2020 and 31 January 2021**

**Defect** The wall thickness of the drop bars on the bike's handles may be too thin and the clamping screws where the drop bars connect to the integrated brake and shifting lever may be tightened (or re-tightened) too tightly. This could cause the drop bar to crack or break.

**Hazard** If the drop bar cracks or breaks, steering control may become loose, increasing the risk of an accident or injury.

**What to do** Consumers should stop using the product. When parts become available from the end of July, Canyon Bicycles will contact consumers to arrange for return of the product and replacement drop bars or a full refund.

**Contact details** Consumers should contact Canyon Bicycles on 1300 712 003 or go to <https://www.canyon.com/en-au/contact/>

**See [productsafety.gov.au](https://productsafety.gov.au) for  
Australian product recall information**