

Product Safety Recall



Childcare Snuggle Time Bedside Sleeper

Model number: 036310-356

Design: Storm Cloud

Barcode number: 9314824024786

Sold exclusively through Baby Bunting
from May 2017- September 2018

In some circumstances the mattress base of the Childcare Snuggle Time Bedside Sleeper may lean very slightly left to right, towards the drop down side (the co-sleeper function side of the product). **Please note there have been no reports of injury as a result.** The fault occurs if:

- The unit has not been set up correctly;
- The unit is placed on an unlevelled surface;
- The unit may have a minor manufacturing variation of 1.5 degrees.

The slight inclination of impacted units may aid infants to roll. Not all units are impacted.

Consumers can use the below steps to determine if they are in possession of an impacted unit:

1. Ensure the Bedside Sleeper is on an even and level floor
2. Remove the mattress from the bedside sleeper
3. Remove the base board and mattress from the mattress cover
4. Place the base board back to the position inside the sleeper where the mattress would usually lie
5. Place a round object (e.g. a pen, a small ball) in the middle of the base board and observe whether it rolls freely to one side. Alternatively, use a spirit level if you have one

What to do: Consumers should first test their unit (see steps above). If they believe that their unit is not level they should contact the distributor to receive a replacement mattress cover which can be placed over the existing mattress of the product to ensure that any impacted units lay flat as intended.

Consumers can contact the distributor by phoning 1800 656 743 Mon-Fri 8:30am-6:30pm or via email at: admin@cnpbrands.com.au. More information can be found online at cnpbrands.com.au

See productsafety.gov.au for Australian product recall information