

ELECTRICAL SAFETY RECALL

Growatt 8.2kw Solar Inverter Model 8000 MTL-S



IDENTIFICATION:

Growatt 8000MTL-S PV Grid Inverter

Serial numbers: PYE2Axxxxx and PYE2Bxxxxx

Manufacture date: 18 January 2021 to 26 February 2021

The inverter was sold and installed by Austra Energy, Bluesun Group and Go Solar in NSW, VIC, and QLD from 1 March 2021 to 26 May 2021.

DEFECT:

The connectors installed with the inverter are of different types and different manufacturers, which does not comply with the electrical safety standards. The incompatible connectors could overheat or melt.

HAZARD:

If the connectors overheat or melt, there is a risk of the connectors catching fire, which may result in an injury or death and/or property damage.

ACTION REQUIRED:

Consumers should check the serial number of the product and should shut down the inverter. Consumers will be contacted by Growatt New Energy Australia to arrange for the inverter to be repaired on site, free of charge.

For further information

Please contact Growatt New Energy Australia on 1800 476 928 or australia@ginverter.com

See www.productsafety.gov.au for Australian product recall information