

Product Safety Recall

Modular Reservoir Assembly

Batch no: 16821 (located on the top cover)



Supplied by Premier Auto Trade, Bursons and vehicle mechanics between 27 August 2021 and 13 September 2021

Defect The product's O-ring does not completely seal. Fuel may leak from the petrol tank while it is being filled.

Hazard If fuel leaks from the petrol tank while it is being filled, there is an increased risk of fire, which may result in serious injury or death.

What to do Affected consumers will be contacted by the mechanic that installed the defective part and asked to bring their vehicle in for a replacement part to be fitted.

Contact details For more information, consumers should contact their mechanic in the first instance. Consumers can contact BorgWarner Australia on 03 9566 4400 or by email at peilin@borgwarner.com

See productsafety.gov.au for
Australian product recall information