

Product Safety Recall

Fixed Webbing Buckle Seat Belt



Sold or installed by vehicle mechanics, vehicle part retailers and seat belt retailers between 1 January 2021 and 1 October 2021

Identification

An aftermarket seat belt buckle that may have been fitted as a replacement part during vehicle repair.

Affected part numbers begin with '1765'.

Part numbers can be found on the underside of the seat belt's label.

Defect

The seat belt's stitching may come apart and the buckle may separate.

Hazard

The seat belt may not properly restrain an occupant, increasing the risk of serious injury or death in the event of an accident.

What to do

Consumers should stop using the seat belt and contact the mechanic that installed it to organise for a replacement to be fitted. If the driver's seat belt is affected, the mechanic will offer to arrange for the vehicle to either be towed to the place of replacement or for a mobile technician to be sent to the vehicle (or similar arrangement), so that the vehicle does not have to be driven to receive a replacement.

For further information

contact Hemco Industries on 1300 065 057 or sales@hemco.com.au

**See productsafety.gov.au for
Australian product recall information**