

PRODUCT SAFETY RECALL



**Willans Silverstone 6-Point Safety Harness
sold by Brabham Automotive and Eastern Race Parts between
7 May 2020 and 10 November 2021**

DEFECT:

Due to a manufacturing error in the release box (Camloc), the harness straps may not release when the release button is pressed.

HAZARD:

The driver may not be able to escape the vehicle without assistance, which could lead to serious injury or death.

ACTION REQUIRED:

Consumers should not use the affected harnesses until the release box has been replaced. Consumers should contact the place of purchase to organise for a replacement release box. Once the new release box has been installed, the old release box ought to be returned to the place of purchase.

For further information

please contact the place of purchase in the first instance. Consumers can contact Eastern Race Parts on 1300 439 526.

**See productsafety.gov.au for
Australian product recall information**