

ELECTRICAL SAFETY RECALL

IMC 523 / 525 Series Food Waste Disposer

Model numbers: F52/301, F52/321, F52/520



IMC 523

IMC 525

IDENTIFICATION:

Model numbers: F52/301, F52/321, F52/520

These units can be recognised by the distinctive black rubber housing above the motor. The product was sold through Food Services Machinery Pty Ltd (FSM) under the following brands:



The product was sold between 2015 and 2021.

DEFECTS:

The rubber seal at the top of the food waste disposer may degrade and allow water to enter the main housing and control box.

HAZARD:

Risk of electric shock, which can cause serious injury or death

ACTION REQUIRED:

Consumers should immediately stop using the equipment and disconnect it from the electricity supply. Contact Lincat Limited to organise for the unit to be decommissioned. Lincat Limited will either provide a replacement unit or a refund.

For further information

Please direct all queries concerning this recall to FSM (Food Service Machinery) Pty Ltd on 03 9368 2300 or sales@fsm-pl.com.au

See www.productsafety.gov.au for Australian product recall information