

Product Safety Recall

Kolder Perimeter Frame Shower Glass Door Panel



Installed by Kolder
between 23 August 2019 and 22 December 2019

Defect

The glass door may not have been toughened correctly, and may not shatter according to the requirements of the Australian toughened glass safety standards.

Hazard

If the glass door has not been toughened correctly and the glass breaks, it may break into fragments or shards and pose a risk of serious injury.

What to do

Consumers will be contacted by Kolder, to arrange for their shower door panel to be replaced, free of charge.

Contact details

For more information, contact Kolder at KolderService@kolder.com.au

See productsafety.gov.au for
Australian product recall information