

Product Safety Recall

Garmin Fusion® Apollo™ Amplifiers

Fusion MS-AP12000 - Monoblock Marine Amplifier

Fusion MS-AP41200 - 4 Channel Marine Amplifier

Fusion MS-AP61800 - 6 Channel Marine Amplifier

Fusion MS-AP82400 - 8 Channel Marine Amplifier



Defect: In certain circumstances, internal components of the amplifier may fail during use, generating excessive heat, smoke and/or a flame.

Hazard: If the amplifier overheats, there may be an increased risk of fire, which may result in serious injury, death, or property damage.

What to do: Consumers should stop using the amplifiers immediately. Consumers should contact an authorised Garmin dealer or service centre to arrange for a repair so a replacement fuse can be installed.

Consumers can review the Garmin service alert at <https://www.garmin.com/en-AU/marine/servicenotices>

Contact details: For more information, consumers can contact Garmin Product Support on 1800 235 822 or visit <https://www.garmin.com/dealerlocator> to locate their nearest Garmin dealer or service centre.

**See productsafety.gov.au for
Australian product recall information**